

**From:** [Coltrain, Katrina](#)  
**To:** [Hayes, Mark](#); [Turner, Philip](#); [Pettigrew, George](#)  
**Cc:** [Patrick.Bond@WestonSolutions.com](mailto:Patrick.Bond@WestonSolutions.com)  
**Subject:** RE: Wilcox Residential Letter Figures and Updated Results Tables  
**Date:** Tuesday, October 06, 2015 3:08:00 PM

---

Good Day, just a few clarification questions.

1. it is noted that Grid 2, Property 21 was not sampled. Will you please indicate why it was not sampled.
2. Grids 4 and 6, Property 6: sludge is indicated at two locations.
  - a. Was this sludge or oil-saturated soil; can a distinction be made?
  - b. Was the thickness of the oil-soil/sludge noted?
  - c. Just to confirm, all borings Grids 3, 4, 5, and 6 were pushed to depth and only the two borings indicated on the map had oil-soil/sludge.

thanks

Katrina Higgins-Coltrain  
Remedial Project Manager  
US EPA Region 6  
LA/OK/NM Section  
1445 Ross Avenue  
Dallas, Texas 75202  
214-665-8143